
Maryland Historical Trust State Historic Sites Inventory Form



PG: 68-41-46
Survey No. (%

Magi No.

DOE __yes __no

not for publication
not for publication
not for publication
not for publication
t
's
museum park private residence religious scientific transportation other:
ses of <u>all</u> owners)
no.:
liber
folio
Maryland
rveys
tate county loca

7.	Descri	p	tic	on
		_		

Survey No. PG: 68-41-46

excellent deteriorated _X unaltered X original site good ruins altered moved date of move fair unexposed	_X good ruins		•	
--	---------------	--	---	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This one story brick structure, was originally constructed as a gas station, Additions were made to the building when it was converted to a tire recapping facility soon after WWII. The most noticeable features of the building are the service bays: two on the front of the building, three on the 43rd Ave, side of the building. There is a diagonal entry way.

For the past 37 years, the building has been used as an auto body repair shop; during this period an addition was made to the rear of the building. Signs painted on the front and side of the building ("Hyattesville Auto Body") apparently date from the early years of its present use. Another alteration to the building is the replacement of glass windows on the corner of the building with plywood inserts.

<u>8. S</u>	ign	ificance			Survey No.	PG: 68-41-46
Period	-1499 -1599 -1699 -1799 -1899	Areas of Significance—C — archeology-prehistoric — archeology-historic — agriculture — architecture — art — commerce — communications		and justify below community planning conservation conomics ducation ngineering xploration/settlement ndustry	landscape archit law literature military music philosophy politics/governm	science sculpture social/ humanitarian theater
Specific	dates	1942-1945	Build	er/Architect	Local	development pattern
check:	an Appli	cable Criteria:A d/or cable Exception:A of Significance:	,	BE		<u>.</u>
Prepare support	both	a summary paragraph o	of si	gnificance and a	general stateme	ent of history and

The historic uses of this building (gas station and tire recapping) as well as its present use, are illustrative of the past and present dominance of automobile related facilities along this section of Rt. 1/Rhode Island Ave. Since 1950 the building has been owned by the same family and operated as an auto body shop. The property has recently been acquired by the County.

This building is scheduled for demolition by Prince George's County within a few months,

9. Major Bibliographical References

Survey No. PG: 68-41-46

- (1) Sandborn Map of Hyattesville 1922, 1933
- (2)Oral interview Dick Curtin Jr.
- (3)Oral interview Francis Geary

1	0.	Ge	ogra	phic	al	Data

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state code county code

state code county code

11. Form Prepared By

name/title Carol Hooper Photo- D. Woods, C. Hooper

organization George Washington University date 4/15/87

street & number 923 N. Highland St. telephone 703 276-1528

city or town Arlington state Virginia

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

